







UNCONTROLLED DRAWING

(DATA SUBJECT TO CHANGE WITHOUT NOTICE)
 FOR ADDITIONAL HELP CONTACT ENGINEERING@ADALET.com



XCBE N4 COVER

- NOTES:
1. MAKE BOX FROM PART #2362-2RW.
 2. REFERENCE DWG #4280-1 FOR STANDARD MACHINING.
 3. MAKE COVER FROM PART #2625-RW.
 4. REFERENCE DWG #4280-2G FOR STANDARD MACHINING.
 5. PROBE OPENING & BACKWALL FOR PROGRAM ZERO (CENTERLINE).

		MODIFIED XCBE N4 ENCLOSURE FOR	
SEE NOTES TUMBLAST XCBE N4	DDH 12-10-05	1-4 D	10F1