





XXXXXX

UNCONTROLLED DRAWING

(DATA SUBJECT TO CHANGE WITHOUT NOTICE)
FOR ADDITIONAL HELP CONTACT ENGINEERING@ADALET.COM



XCBSAQ N4 COVER

- NOTES:
1. MAKE BOX FROM XCBSAQ PART #6171-HRW.
 2. REF DRAWING # XXXX FOR BOX STANDARD MACHINING.
 3. MAKE COVER FROM XCBSAQ PART #6172-HRW.
 4. REF DRAWING # XXXXX FOR COVER STANDARD MACHINING.
 5. PROBE OPENING FOR PROGRAM ZERO (CENTER LINE).

		MODIFIED XCBSAQ N4 ENCLOSURE FOR	
DATE: 7-11-97 DRAWN BY: DDH CHECKED BY: D TOLERANCE: 10F1 SEE NOTES TUMBLAST XCBSAQ N4	DATE: 7-11-97 DRAWN BY: DDH CHECKED BY: D TOLERANCE: 10F1 SEE NOTES TUMBLAST XCBSAQ N4	DATE: 7-11-97 DRAWN BY: DDH CHECKED BY: D TOLERANCE: 10F1 SEE NOTES TUMBLAST XCBSAQ N4	DATE: 7-11-97 DRAWN BY: DDH CHECKED BY: D TOLERANCE: 10F1 SEE NOTES TUMBLAST XCBSAQ N4