







# UNCONTROLLED DRAWING

(DATA SUBJECT TO CHANGE WITHOUT NOTICE)  
 FOR ADDITIONAL HELP CONTACT [ENGINEERING@ADALETT.COM](mailto:ENGINEERING@ADALETT.COM)



NOTES:

1. MAKE BOX FROM PART #2572-3RW.
2. REFERENCE DWG. #4283-1 FOR STANDARD MACHINING.
3. MAKE COVER FROM PART #2573-RW.
4. REFERENCE DWG. #4283-2 FOR STANDARD MACHINING.
5. PROBE OPENING & BACKWALL FOR PROGRAM ZERO (CENTERLINE).

		MODIFIED XCBF N4 ENCLOSURE FOR	
DATE: 12-10-05 TIME: 10:00 AM USER: DDH	SEE NOTES TUMBLAST XCBF N4	DDH	12-10-05 1-4-05 D 10F1